

CASE SHARING

CRP II CALIBRATION ISSUE ON BS 240

PRESENTED BY HASSINA SALAH
CLINICAL APPLICATION SPECIALIST
IVD CLINICAL DEPARTMENT SERVICE DEVISION

AGENDA


1- ISSUE

2- ESCALATION AND DATA ANALYSIS

3- SOLUTION AND CONCLUSION

4- SUMMARY

1- ISSUE



- Where : Private laboratory in Algiers
- Machine model : BS 240 newly installed
- ISSUE : **CRP II calibration failed**
- Flag : **MON**
- Reagent lot number : 148923007
Expiration date : 2024-12-04
- Calibrator lot number : 150723001
Expiration date : 2024-07-31
- QC lot number : no information
- Customer calibrated CRP II 3 times with the same results and flag.

The third level calibration results was lower than the second. It causes **MON** flag.

2- ESCALATION AND DATAS ANAYNSIS


- DATA ANALYSIS

Calibrators	Standard responses	Calibration failed response					
		1st Cal	1st Bias	2nd Cal	2nd Bias	3rd Cal	3rd Bias
Water	232.4	41.3	-82.229%	53.1	-77.151%	20.7	-91.093%
CRP cal 2	527.1	118.1	-77.594%	131	-75.147%	142.4	-72.984%
CRP cal 3	1184.1	73.4	-93.801%	74.8	-93.683%	76.9	-93.506%
CRP cal 4	2503	1811.6	-27.623%	1875	-25.082%	1857	-25.801%
CRP cal 5	3680.7	2552	-30.665%	2583	-29.818%	2572	-30.114%
CRP cal 6	5657.5	3717	-34.300%	3739	-33.904%	3690	-34.784%

Compared to the factory reference calibration curve, the response of the first 3 levels are significantly lower. Considering these levels are related to water and dilution calibration, it should be the issue of water and dilution calibration.

2- ESCALATION AND DATAS ANALYSIS

- HYPOTHESIS



2- ESCALATION AND DATAS ANALYSIS

- VERIFICATION - Reagent

Reagent Integrity

- no problem reported with this lot in other laboratories.
- Changed reagent bottle (same lot) ran a new calibration with the same result.

Reagent Settings

- Parameter settings are normal.
- Calibration settings are normal.
- Calibration dilution settings are normal.



Unlikely to be caused by reagent.



2- ESCALATION AND DATAS ANALYSIS

- VERIFICATION – Analyzer & Calibrator

Calibrator

- Calibrator was replaced and with the same result.
- Calibrator volume is enough.



Analyzer


- The analyzer was newly installed.
- Service engineer checked the analyzer and ensured the machine was working normally, but the recalibration failed with the same result.

Unlikely to be caused by calibrator or analyzer.


2- ESCALATION AND DATAS ANALYSIS

- VERIFICATION - Consumables

Considering the responses of the first 3 levels are significantly lower, the water quality should be questioned, so reaction curve of DI water was checked.



Reaction curve of DI water level




Standard water reaction curve

The reaction curve of DI water level was increasing during incubation period, which indicates interference from water. It tells us that the water quality was not good, causing lower results in the calibration levels related to DI water.


3- SOLUTION AND CONCLUSION



CRP II calibration curve result with good DI water



CRP II water reaction curve with the new DI water




QC level 1 and 2 near to the target value

DI water was changed and a new calibration was run

- The calibration passed
- QC on the target value.

4- SUMMARY



Thank **you!**